UP

bridge the gap

Quick start guide
get your UP board ready in 3 easy steps

- - - step 1 - - -

Basic setup of the board and accessories

- ☑ Is the heat sink attached to the CPU
- ☑ Is the RTC Battery plugged in the pin header
- ☑ Power adapter with 3A@5V. 5.5/2.1mm DC jack
- ☑ HDMI cable with type A male connector
- ☑ Keyboard & mouse to control your up board

- - - step 2 - - -

Prepare your bootable drive with the operating system of choice

Download Windows ISO file and store it in bootable USB with 'Windows USB/DVD Download Tool' (Windows ISO file is purchaseable from Microsoft store)

Windows 8.1 / 10 drivers & Windows installation guide are available at:
up-community.org/index.php/downloads

To prepare another (linux or android based) operating system, please visit our UP community page

up-community.org/index.php/downloads

ubilinux
yocto PROJECT

- - - step 3 - - -

Connect your UP board in the following sequence

- ☑ bootable USB drive with ISO or OS preload
- ☑ HDMI cable to your monitor, Keyboard+ mouse
- ☑ Power DC cable (this will power on the board)
- ☑ Switch to the correct HDMI input
- ☑ Wait for the UP BIOS logo!

HDMI

UP

Bootable USB