


Solid State Relays Accessories Type RHS... Heatsink Assemblies
































Type RHS 301
Heatsink assembly for 1-phase and 3-phase SSRs.

2 screws M4 x 6 mm 4 x Selftapping screws M4 x 9.5 mm Ozo DIN rail adapter Type RHS 00 1 single-phase relay not included 2 screws M5 x 8 mm 2 washers Ø 5.4 x 10 mm Heatsink $R_{\text{thSA}} = 0.8 \; \text{K/W}$ Max mounting torque 1.5 Nm 2 screws M4 x 6 mm 4 x Selftapping screws M4 x 9.5 mm . B HEATSINK COMPOUND DIN rail adapter Type RHS 00 2 single-phase relays **not included** 0 DIN rail adapter Type RHS 00 Heatsink $R_{thSA} = 0.8 \text{ K/W}$ 2 screws M4 x 6 mm 4 screws M5 x 8 mm 4 washers Ø 5.4 x 10 Con Contraction of the Contracti 4 washers Ø 5.4 x 10 mm Max mounting torque 1.5 Nm 4 x Selftapping screws M4 x 9.5 mm Thermal resistance versus 1.5 3-phase relay power dissipation not included 1.3 1.2 0 0.8 0.7 0.5 0.4 0.3 HEATSINK COMPOUND 0.2 4 screws M5 x 8 mm Heatsink 4 washers Ø 5.4 x 10 mm $R_{thSA} = 0.8 \text{ K/W}$ Max. mounting torque 1.5 Nm