



REV.	DESCRIPTION/ECO NO.	DATE
	RELEASED	3/24/10



NOTES:

1. OPENING FOR FLEX TAPE.
2. OPERATION:
 1. GENTLY PULL DARK TABS AWAY FROM WIRES
 2. INSERT FLEX TAPE WITH CONTACTS UP
 3. PUSH DARK TABS BACK TOWARDS WIRES TO LOCK FLEX TAPE IN PLACE.
 4. DO NOT USE IF CONTACTS HAVE SOLDER BUILD UP ON THEM.
3. LIMIT CURRENT TO A MAXIMUM OF 5 AMPS.

METRIC  THIRD ANGLE PROJECTION	DIMENSIONS ARE IN MILLIMETERS		JKL COMPONENTS CORPORATION TITLE NO SOLDER FLEX TAPE CABLE CONNECTOR			
	TOLERANCE UNLESS OTHERWISE SPECIFIED 1 PL +/- REF. 2 PL +/- REF. ANGLE +/-					
DRAWN BY L. WENGSTROM	APPV'D BY L.R.	DATE 3/24/10	SIZE A	FSCM NO. 55335	DRAWING NO. ZFS-CH205-J	
- CAD DRAWING - MANUAL REVISIONS NOT PERMITTED			SCALE NOT TO SCALE	RELEASED DATE 3/24/10	REVISION DATE	REV. NO. SHEET 1 OF 1