



Dimensions of Geared Model



Dimensions of Geared Model



Ratios of Geared Model

Gear Ratio	6/25	1/5	3/25	1/10	2/25	1/15	3/50	1/20
Ordinary Torque	400mN·m							
Destruction Torque	1200mN·m							

Gear Ratio	1/25	1/30	1/50	1/60
Ordinary Torque	700mN·m			
Destruction Torque	2100mN·m			

Gear Ratio	2/125	1/75	3/250	1/100	1/125	1/150	1/250	1/300
Ordinary Torque	1000mN·m							
Destruction Torque	3000mN·m							

Ratios of Geared Model

Gear Ratio	1/3	1/5	2/15	1/10	2/25	1/15	1/20
Ordinary Torque	400mN·m			500mN·m		600mN·m	800mN·m
Destruction Torque	1200mN·m			1500mN·m		1800mN·m	2400mN·m

Gear Ratio	1/25	1/30	1/50	1/60
Ordinary Torque	900mN·m	1100mN·m	1600mN·m	
Destruction Torque	2700mN·m	3300mN·m	4800mN·m	

Gear Ratio	1/75	1/100	1/125	1/150	1/180
Ordinary Torque	2500mN·m				
Destruction Torque	7500mN·m				