



- Rev 2:
- added speaker connections for 38i socket
 - changed record divider to approx 5:1 and applied to 386 also
 - eliminated channel and sound rate jumpers (Omron 9889)
 - added 12V regulator for 38i 12V pin

Title		Rev	
QV430PASCCH		1-3	
Step Modem Programmer		of	
Date	01/14/03	Drawn by	1-3
Filename	QV430PASCCH	Sheet	1